Hardware Installation Manual
## Standard Mount

1. Components

Mount

Hardware Set

## 2. Assembling EyeRIS & USB cable on standard mount

Step 1 – Use Allen key provided in hardware set to unscrew only one screw as shown below & remove the L-plate.

**Step 2 –** Unscrew both M3 screw using PH 0 screwdriver & remove the plate as shown below:

Step 3 – Take USB cable provided in the box and insert "Type-A" connector end of the USB cable through mount as shown below:

Type-B Connector

Type-A Connector

Step 4 – Fix EyeRIS on plate using M6 screw
provided in the hardware set.
Use PH 2 screw driver

Step 5 – Use M3 screw and PH 0 screw driver to secure the plate on the mounting rod as
shown below:

**Step 6 –** Use Allen key to secure the L-plate and the USB cable in mounting rod.

Step 7 – Connect USB cable "Type B" connector to the EyeRIS and it is ready to be installed
on the wall

3. Installation of EyeRIS

**Step 1 –** Measure 33"from the floor & fix the whiteboard on the wall at the desired location.

**Step 2 –** Mark the centre of the whiteboard as shown in the diagram below:

**Step 3 –** Place the EyeRIS mount on the wall & mark the holes as shown:

**Step 4 –** Use a drill machine to drill holes on the wall at the marked location.

Step 5 – Fix the EyeRIS mount on the wall using plastic sleeve anchors & screws provided in the hardware set.

Fastener
in hole on wall

Step 6 – Place the whiteboard on the wall.

Step 7 - Stick OPTIBAR strips on whiteboard as shown below (Optional) & proceed for calibration.

Projection area

4. Finished setup

1. Projection Area
2. Optibar
3. Stylus
4. EyeRIS 8090UST
5. Projector
6. PC/Laptop
7. VGA or HDMI Cable
8. USB Cable